



This part should be printed, cut out and glued to a piece of Perspex before being cut to shape.



Walking Machine	2010
PracticalStudent.com	
Part Number : 16	
Part Name : 1018 Gear	
Material : Perspex	A4
Required : 4	16/09/10
Drawing 16 of 17	